

## Illinois Tollway Base Sheet Revisions

Drawing	Drawings Modification Summary Effective: 03-31-2016
All	The electronic (pdf) version of the Standard Drawing are now made searchable (text).
	Erosion Sediment Control (ESC)-Series 200
	Sediment Basin Dewatering Device
	Revised Note 7, removed proprietary name from skimmer device.
	Roadway (RDY)-Series 400
M-RDY-408	Approach Slab, Mainline
	Changed Transverse Reinforcement size and spacing in the bottom mat of the bridge approach slab and transition apshoulder slabs from #6@9" to #8@4" to be in conformance with IDOT ABD Memo 15.8.
	Changed Transverse Reinforcement size and spacing in the top mat of the bridge approach slab and transition approach slabs from #5@12" to #5@6" to be in conformance with IDOT ABD Memo 15.8.
	Changed Longitudinal Reinforcement size and spacing in the top mat of the bridge approach slab and transition appr shoulder slabs from #4@15" to #5@6" to be in conformance with IDOT ABD Memo 15.8.
	Added note *** to clarify that base sheet reinforcement is for approach slabs not located on retaining walls. If approach splaced on retaining wall, reinforcement shall be designed for TL-5 crash loading.
	Changed spacing and shape of both dxx vertical bars in the barrier on the bridge approach slab and transition approashoulder slab to match the vertical bars in the bridge parapet and moment slab barrier.
All	Changed top mat reinforcement cover to 2.25" to be consistent with deck and moment slab clearances.
Sheets 1,2	Updated Note to Designer for Drainage Structures. Designer to determine size, type and location.
Sheets 1,2	Changed approach slab shoulder width requirements to match Structures Design Manual.
Sheet 3	Added option of using subgrade aggregate, special under the transition approach slab.
Sheet 3	Added additional Approach Slab Barrier Elevation to distinguish between non-integral and integral/semi-integral abutr
	Eliminated Optional Longitudinal Joint Within a Traffic Lane detail.
	Changed Neoprene Sheet to Elastomeric Sheet to keep call out generic and not specific.
	Revised Bill of Material to clarify Pay Items and Pay Item Numbers to be included.  Added note to Typical Barrier Transition Detail to clarify where the 1'-9" dimension should be measured.
M-RDY-409	Approach Slab, Ramp
	Changed Transverse Reinforcement size and spacing in the bottom mat of the bridge approach slab and transition ap shoulder slabs from #6@9" to #8@4" to be in conformance with IDOT ABD Memo 15.8.
All	Changed Transverse Reinforcement size and spacing in the top mat of the bridge approach slab and transition appro shoulder slabs from #5@12" to #5@6" to be in conformance with IDOT ABD Memo 15.8.
All	Changed Longitudinal Reinforcement size and spacing in the top mat of the bridge approach slab and transition approach slabs from #4@15" to #5@6" to be in conformance with IDOT ABD Memo 15.8.
	Added note *** to clarify that base sheet reinforcement is for approach slabs not located on retaining walls. If approach is placed on retaining wall, reinforcement shall be designed for TL-5 crash loading.
All	Changed spacing and shape of both dxx vertical bars in the barrier on the bridge approach slab and transition approa shoulder slab to match the vertical bars in the bridge parapet and moment slab barrier.
	Changed top mat reinforcement cover to 2.25" to be consistent with deck and moment slab clearances.
	Updated Note to Designer for Drainage Structures. Designer to determine size, type and location.  Changed approach slab shoulder width requirements to match Structures Design Manual.
	Added option of using subgrade aggregate, special under the transition approach slab.
	Added additional Approach Slab Barrier Elevation to distinguish between non-integral and integral/semi-integral abutr
	Eliminated Optional Longitudinal Joint Within a Traffic Lane detail.
	Changed Neoprene Sheet to Elastomeric Sheet to keep call out generic and not specific.
Sheet 5	Revised Bill of Material to clarify Pay Items and Pay Item Numbers to be included.
Sheet 5	Added note to Typical Barrier Transition Detail to clarify where the 1'-9" dimension should be measured.
M-RDY-410	Reserved
	Emergency Turnaround Median Width <u>&gt;</u> 35 Ft
	Bridge (BRG)-Series 500
	Expansion Joint Repair Base Sheet was removed since details did not match Special Provision.
	Crash Wall Modifications Median Piers
M-BRG-507	Crash Wall Modifications Median Piers  Note 4 - Changed Reinforcing bars to Reinforcement Bars.
M-BRG-507 M-BRG-508	
M-BRG-507 M-BRG-508	Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Crash Wall Modifications Shoulder Piers  Note 4 - Changed Reinforcing bars to Reinforcement Bars.
M-BRG-507 M-BRG-508	Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Crash Wall Modifications Shoulder Piers  Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Slopewall Details
M-BRG-507 M-BRG-508 M-BRG-525	Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Crash Wall Modifications Shoulder Piers  Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Slopewall Details  Drainage (DRN)-Series 600
M-BRG-508 M-BRG-525 M-DRN-601	Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Crash Wall Modifications Shoulder Piers  Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Slopewall Details  Drainage (DRN)-Series 600  Slope Drain
M-BRG-508 M-BRG-525 M-DRN-601	Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Crash Wall Modifications Shoulder Piers  Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Slopewall Details  Drainage (DRN)-Series 600
M-BRG-508 M-BRG-525 M-DRN-601	Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Crash Wall Modifications Shoulder Piers  Note 4 - Changed Reinforcing bars to Reinforcement Bars.  Slopewall Details  Drainage (DRN)-Series 600  Slope Drain  Revised storm sewer to "Class B, 12".

Base Sheet	
Drawing	Modification Summary Effective: 03-31-2016
M MOT 700	Maintenance of Traffic (MOT)-Series 700
M-MO1-700	Temporary Concrete Barrier "Y" Connector Segment
	Revised Barrier Details Notes.  Changed barrier edges chamfered from 1/2" to 1" on all edges (optional).
	Changed barrier edges chamiered from 1/2 to 1 on all edges (optional).
	Overhead Sign (OHS)-Series 720
M-OHS-720	Overhead Sign Structure Span Type Summary and Total Bill of Material
0110 120	Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
M-OHS-721	Overhead Sign Structure Cantilever Type Summary and Total Bill of Material
	Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
M-OHS-722	Overhead Sign Structure Entrance Monotube Type (Steel) Mainline Summary and Total Bill of Materia
	Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
	Clarified Concrete Structures is for Single Face Barrier and included in Summary Table and Total Bill of Mate
M-OHS-723	Overhead Sign Structure Exit Monotube Type (Steel) Mainline Summary and Total Bill of Material
	Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
	Clarified Concrete Structures is for Single Face Barrier and included in Summary Table and Total Bill of Mate
M-OHS-724	Overhead Sign Structure Butterfly Type (Steel) Summary and Total Bill of Material
	Added Protective Coat (SQ YD) to Summary Table
<u> </u>	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
<u> </u>	Removed Truss Extension for Mounting Walkway detail and references
<u> </u>	Added "L" column and removed TGL and TGL1 from the Summary Table
M OUG 705	Overhead Cian Structure Entrance Manetube Type (Steel) AET Bown Symmetry and Tatal Difference
W-OH5-725	Overhead Sign Structure Entrance Monotube Type (Steel) AET Ramp Summary and Total Bill of Mate
	Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.  Clarified Concrete Structures is for Single Face Barrier and included in Summary Table.
	Clarined Concrete Structures is for Single Face Barrier and included in Summary Table.
M OUS 726	Overhead Sign Structure Exit Monetules Type (Steel) AET Bomp Summery and Total Bill of Metarial
WI-OH3-720	Overhead Sign Structure Exit Monotube Type (Steel) AET Ramp Summary and Total Bill of Material  Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
	Clarified Concrete Structures is for Single Face Barrier and included in Summary Table.
	Clarified Concrete Structures is for Single Face Barrier and included in Summary Fable.
M-OHS-727	Overhead Sign Structure Exit Monotube Type (Steel) Cash-IPO Ramp Summary and Total Bill of Mate
10110-121	Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
	Clarified Concrete Structures is for Single Face Barrier and included in Summary Table.
	The same and the s
M-OHS-728	Overhead Sign Structure Span Type (Steel) Summary and Total Bill of Material
	Added Protective Coat (SQ YD) to Summary Table
	Clarified Class SI and Class DS Concrete are included in Foundation For Overhead Sign Structure.
M-OHS-729	Overhead Sign Structure ITS Gantry Frame (Steel) Single Span Structure Details
Sheet 1	Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.
Sheet 4	Removed Note 6, referring to ASTM requirements of HSS members.
	Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.
Sheet 5	to the district of the distric
Sheet 5	Removed Protective Coat quantity since not required to be applied to shoulder foundation.
Sheet 5 Sheet 5	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.
Sheet 5 Sheet 5 Sheet 6	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.
Sheet 5 Sheet 5 Sheet 6 Sheet 6	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.
Sheet 5 Sheet 5 Sheet 6	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 8	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 8	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added anchor 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000  M-ITS-1001	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet  Dynamic Message Sign (ITS) - Series 1100
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000  M-ITS-1001	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet  Dynamic Message Sign (ITS) - Series 1100  Revised conduit call-outs
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000  M-ITS-1100  M-ITS-1100	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet  Dynamic Message Sign (ITS) - Series 1100  Revised conduit call-outs  Revised conduit call-outs
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000  M-ITS-1100  M-ITS-1100	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet  Dynamic Message Sign (ITS) - Series 1100  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Removed pad mounted transformer.  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Revised Note 2 to eliminate 120/208V and pad mount.
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000  M-ITS-1001  M-ITS-1100  M-ITS-1100  M-ITS-1100	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet  Dynamic Message Sign (ITS) - Series 1100  Revised conduit call-outs  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Removed pad mounted transformer.  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Revised Note 2 to eliminate 120/208V and pad mount.  Cabinet Wiring-Series 1200
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000  M-ITS-1100  M-ITS-1100  M-ITS-1100  M-ITS-1100	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet  Dynamic Message Sign (ITS) - Series 1100  Revised conduit call-outs  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Removed pad mounted transformer.  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Revised Note 2 to eliminate 120/208V and pad mount.  Cabinet Wiring-Series 1200  Cabinet Wiring
Sheet 5 Sheet 5 Sheet 6 Sheet 6 Sheet 7  M-OHS-730 Sheet 1 Sheet 4 Sheet 6 Sheet 6 Sheet 6 Sheet 7 Sheet 7 Sheet 7 Sheet 7 Sheet 8  M-ITS-1000  M-ITS-1001  M-ITS-1100  M-ITS-1100  M-ITS-1104  M-ITS-1104	Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Overhead Sign Structure ITS Gantry Frame (Steel) Two-Span Structure Details  Revised Material Specification Table to specify ASTM A500 Gr C & B for Frame & Mounting Beam HSS, respectively.  Removed Note 6, referring to ASTM requirements of HSS members.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Updated anchor bolt note to allow ASTM F1554 bolts.  Revised Note 1 to clarify requirements for Contractor when soil conditions are not met in the field.  Removed Protective Coat quantity since not required to be applied to shoulder foundation.  Added note 5 to clarify limits of protective coat and revised protective coat quantity in Median Foundation Schedule.  Pole Assembly-Series 1000  ELEVATION VIEWS POLE MOUNTED ITS ELEMENT ASSEMBLY  Added 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL.  GENERAL NOTES POLE MOUNTED ITS ELEMENT ASSEMBLY  Added Note 16 regarding disconnect switch usage.  ITS STANDARD FOUNDATION: New Sheet  Dynamic Message Sign (ITS) - Series 1100  Revised conduit call-outs  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Removed pad mounted transformer.  Revised 30A-2P NEMA 4X DISC MTD ON SUPPORT DETAIL. Revised Note 2 to eliminate 120/208V and pad mount.  Cabinet Wiring-Series 1200

	Page Shoot	Drowings
	Base Sheet Drawing	Modification Summary Effective: 03-31-2016
Tollway Bas	se Sheet Rev	
		Weigh-In-Motion - Series 1600
Section M		WEIGH-IN-MOTION CABINET AND FOUNDATION DETAILS
		WEIGH-IN-MOTION IP CAMERA DETAILS WEIGH-IN-MOTION LOOP DETECTOR DETAILS
		WEIGH-IN-MOTION LOOP DETECTOR DETAILS WEIGH-IN-MOTION DETECTOR LOOP AND QUARTZ SENSOR DETAIL
		INSTALLATION DETAIL DETECTOR HOUSING & DETECTOR HOUSING ADAPTER
		WEIGH-IN-MOTION DETECTOR HOUSING DETAIL
		Flashing Sign Beacon - Series 1700
		FLASHING SIGN BEACON INSTALLATION BREAKAWAY ELECTRICAL DETAIL
	M-115-1701	FLASHING SIGN BEACON INSTALLATION WIRING DIAGRAM
		Conduit Details at Integral Abutment-Series 1900
	M-ITS-1900	CONDUIT DETAILS AT INTEGRAL ABUTMENT BRIDGE STANDARD SLOPE WALL
		Postinos Costano (PHO), Costino 0500
	M-BUS-2500	Business Systems (BUS)- Series 2500  CABLE CONDUIT SCHEDULE AND GENERAL NOTES
		LEGEND SYMBOL LIST, ABBREVIATIONS AND EQUIPMENT SCHEDULES
	M-BUS-2502	SINGLE LINE DIAGRAM AND UTILITY POWER CABLE/CONDUIT SCHEDULE
		CONTROL BUILDING LIGHTING PLAN AND MISCELLANEOUS DETAILS - MAIN PLAZA
		CONTROL BUILDING LIGHTING PLAN AND MISCELLANEOUS DETAILS - REMOTE PLAZA CONTROL BUILDING GROUNDING DETAILS - MAIN PLAZA
		CONTROL BUILDING GROUNDING DETAILS - MAINT LAZA  CONTROL BUILDING GROUNDING DETAILS - REMOTE PLAZA
		GROUNDING SCHEMATIC
		CONTROL BUILDING MISCELLANEOUS DETAILS
		UPS SINGLE LINE AND WIRING DIAGRAM MISCELLANEOUS SCHEMATIC DIAGRAMS
		VIDEO POWER JUNCTION BOX DETAIL - MAIN PLAZA
		VIDEO POWER JUNCTION BOX DETAIL - REMOTE PLAZA
		VIDEO WATCHDOG CAMERA DETAILS
		RAMP PLAZA MONOTUBE DETAILS ACM AND IPO LANES  LOOP JUNCTION BOX DETAIL
		CONTROL BUILDING LIGHTING AND RECEPTACLE PLAN - MAIN PLAZA
		CONTROL BUILDING LIGHTING AND RECEPTACLE PLAN -REMOTE PLAZA
		MISCELLANEOUS CROSS SECTION DETAILS COMED TRANSFORMER PAD DETAIL
		ELECTRICAL SITE PLAN - ACM AND IPO LANES
		UNDERGROUND ELECTRICAL PLAN - ACM AND IPO LANES - MAIN PLAZA
		PLAZA I-PASS PLANS - ACM AND IPO LANES
		UNDERGROUND ELECTRICAL PLAN - ACM AND IPO LANES - REMOTE PLAZA AUTOMATIC LANE ISLAND PLAN AND DETAILS 12 FOOT WIDE LANE
		IPASS ONLY (IPO) LANE ISLAND PLAN AND DETAILS 12 FOOT WIDE LANE
		TOLL EQUIPMENT WIRING DIAGRAM - ACM AND IPO LANES
		LOOP AND TREADLE INSTALLATION DETAILS - ACM AND IPO LANES
		CONTROL BUILDING TSIC - ACM AND IPO LANES - MAIN PLAZA CONTROL BUILDING TSIC - ACM AND IPO LANES - REMOTE PLAZA
		TSIC TERMINAL BLOCK LAYOUT - ACM AND IPO LANES
	M-BUS-2531	CONTROL BUILDING EQUIPMENT LAYOUT - ACM AND IPO LANES - MAIN PLAZA
		CONTROL BUILDING EQUIPMENT LAYOUT - ACM AND IPO LANES - REMOTE PLAZA
		CONTROL BUILDING R3 RACK - MAIN PLAZA CONTROL BUILDING R3 RACK - REMOTE PLAZA
		MISCELLANEOUS DETAILS -ACM AND IPO LANES
		PANELBOARD SCHEDULES FOR TP1 AND TP2 - ACM AND IPO LANES
		PANELBOARD SCHEDULES FOR MDP AND UPS UNITS - ACM AND IPO LANES
		FIBER INTERCONNECTIONS BETWEEN MAIN AND REMOTE PLAZAS - ACM AND IPO LANES PLAZA LANE CONTROL SIGNAL - ACM AND IPO LANES
		TRAFFIC LIGHT DETAILS - ACM LANES
		TRAFFIC LIGHT DETAILS - IPO LANES
		ELECTRICAL SITE PLAN AET LANES UNDERGROUND CONDUIT PLAN - MAIN PLAZA
		UNDERGROUND CONDUIT PLAN - MAIN PLAZA  UNDERGROUND CONDUIT PLAN - MAIN PLAZA PLAN - REMOTE PLAZA
	M-BUS-2545	CONTROL BUILDING EQUIPMENT LAYOUT - REMOTE PLAZA
		CONTROL BUILDING EQUIPMENT LAYOUT - MAIN PLAZA
		CONTROL BUILDING TSIC - MAIN AND REMOTE PLAZAS - AET LANES TSIC TERMINAL BLOCK LAYOUT - ACM AND IPO LANES REMOTE PLAZAS - AET LANES
		PANELBOARD SCHEDULES - MAIN PLAZA AET LANES
	M-BUS-2550	PANELBOARD SCHEDULES - REMOTE PLAZA AET LANES
		WIRING DIAGRAM - AET 3 LANE LAYOUT
		WIRING DIAGRAM - AET 3-LANE LAYOUT  LOOP PLAN - AET 1-LANE LAYOUT
		LOOP PLAN - AET 1-LANE LATOUT  LOOP PLAN - AET 3-LANE LAYOUT
		VES WASH SYSTEM ENCLOSURE DETAIL
		VES WASH SYSTEM PANEL DETAIL VES WASH SYSTEM FLOW DIAGRAM AND MECHANICAL DETAIL
		VES WASH SYSTEM FLOW DIAGRAM AND MECHANICAL DETAIL VES WASH SYSTEM SUGGESTED CONDUIT ROUTING
	M-BUS-2559	VES WASH SYSTEM MISCELLANEOUS POWER WIRING DIAGRAM
	M-BUS-2560	VES WASH SYSTEM CONTROL SWITCH SCHEMATIC







FOUNDATION PLAN VIEW

NOTE TO DESIGNER

THIS BASE SHEET SHOWS TYPICAL NEW CONSTRUCTION
BUT IT IS NOT A STANDARD DRAWING. IT REQUIRES
COMPLETION BY THE DESIGNER PRIOR TO INSERTION INTO
A CONTRACT. MICROSTATION FILES AND THE "CADD
STANDARDS MANUAL" ARE AVAILABLE ON THE ILLINOIS
TOLLWAY WEBSITE. THE DESIGNER SHALL ACCEPT THE
RESPONSIBILITY OF THE DESIGN OF THIS SHEET UPON
ITS COMPLETION AND INSERTION INTO A CONTRACT. ALL
"NOTE TO DESIGNER" BOXES SHALL BE REMOVED PRIOR
TO INSERTION OF THE DRAWING INTO THE PLAN SET.



- 1. CONCRETE, MINIMUM 3000 PSI, 28 DAY COMPRESSIVE STRENGTH.
- 2. DIMENSIONS OF CONCRETE BASE ARE MINIMUM RECOMMENDED. FINAL DIMENSIONS SHALL BE DETERMINED BY A LICENSED STRUCTURAL
- 3. ALL EXPOSED CONDUIT SHALL BE PVC COATED GALVANIZED STEEL UNLESS OTHERWISE NOTED.




## FOUNDATION SIDE VIEW

M-ITS-1301



ROADWAY WEATHER INFORMATION SYSTEM

DATE 1-31-2015



DUPLEX RECEPTACLE WIRING DIAGRAM

# RPU ENCLOSURE EQUIPMENT SCHEDULE

ID	DESCRIPTION
Α	DUPLEX RECEPTACLE
В	GROUNDING LUG
С	SURGE SUPPRESSOR
D	POWER SUPPLY
Ε	BACK PANEL/BACK PLANE
F	EXPANSION BOARD
G	SERIAL DATA SURGE SUPPRESSOR
Н	PROCESSOR BOARD
I	COMMUNICATIONS BOARD
J	TERMINATION BOARD
K	ANALOG TO DIGITAL CONVERTER
L	CELLULAR MODEM
İм	CISCO IE3000-8TC-E SWITCH
LN_	FIBER OPTIC CABLE PATCH PANEL

## EQUIPMENT/SENSOR SCHEDULE

DESCRIPTION	QTY
SUB-SURFACE TEMPERATURE PROBE	1
ROAD SURFACE STATE SENSOR	2
ROAD SURFACE TEMPERATURE SENSOR	2
AIR TEMPERATURE/RELATIVE HUMIDITY SENSOR	1
CLASSIFYING PRECIPITATION AND VISIBILITY SENSOR	1
WIND SPEED & DIRECTION SENSOR	1
BAROMETRIC PRESSURE SENSOR	1
LATTICE TOWER & FOUNDATION	1
RPU ENCLOSURE	1
REMOTE SENSOR POLE	1

THIS BASE SHEET SHOWS TYPICAL NEW CONSTRUCTION BUT
IT IS NOT A STANDARD DRAWING, IT REQUIRES COMPLETION BY
THE DESIGNER PRIOR TO INSERTION INTO A CONTRACT.
MICROSTATION FILES AND THE "CADD STANDARDS MANUAL" ARE
AVAILABLE ON THE ILLINOIS TOLLWAY WEBSITE. THE DESIGNER
SHALL ACCEPT THE RESPONSIBILITY OF THE DESIGN OF THIS
SHEETUPON ITS COMPLETION AND INSERTION INTO A CONTRACT.
ALL "NOTE TO DESIGNER" BOXES SHALL BE REMOVED PRIOR TO
INSERTION OF THE DRAWING INTO THE PLAN SET.


M-ITS-1302




ROADWAY WEATHER INFORMATION SYSTEM

DATE

1-31-2015





THIS BASE SHEET SHOWS TYPICAL NEW CONSTRUCTION
BUT IT IS NOT A STANDARD DRAWING. IT REQUIRES
COMPLETION BY THE DESIGNER PRIOR TO INSERTION INTO
A CONTRACT. MICROSTATION FILES AND THE "CADD
STANDARDS MANUAL" ARE AVAILABLE ON THE ILLINOIS
TOLLWAY WEBSITE. THE DESIGNER SHALL ACCEPT THE
RESPONSIBILITY OF THE DESIGN OF THIS SHEET UPON ITS
COMPLETION AND INSERTION INTO A CONTRACT. ALL "NOTE
TO DESIGNER" BOXES SHALL BE REMOVED BY THE DESIGNER
PRIOR TO INSERTION OF THE SHEET INTO THE PLAN SET.

LASERS SENSORS MUST BE LOCATED WITHIN 50 FEET
(ON DIAGONAL) OF THE AIM POINT ON THE BRIDGE
DECK SURFACE.

## NOTES:

- 1. DECK SENSORS SHALL BE AIMED AT THE CENTER OF LANE 1, 8' EAST OF THE BRIDGE DIAPHRAGM ON THE BRIDGE DECK.
- 2. APPROACH SENSORS SHALL BE AIMED AT THE CENTER OF LANE 1, 15' WEST OF THE BRIDGE DIAPHRAGM ON THE APPROACH PAVEMENT.
- 3. TYPE V CABLES MAY BE USED FOR RUNS UP TO 1000' BETWEEN THE SENSOR(S) AND THE RPU. WITH APPROVAL OF THE ILLINOIS TOLLWAY, FOR CABLE RUNS 500' OR LESS, MANUFACTURER APPROVED INDIVIDUAL CABLES CAN BE USED BETWEEN THE SENSOR(S) AND THE RPU. THE POLE MOUNTED JUNCTION BOX IS NOT REQUIURED WHEN INDIVIDUAL CABLES ARE USED.
- 4. RODENT PROTECTION SHALL BE USED AS INDICATED IN THE SPECIAL PROVISIONS.
- 5. FOR BRIDGE MOUNTING APPLICATIONS, THE DESIGNER SHALL DEVELOP STRUCTURAL FOUNDATION AND POLE MOUNTING DETAILS,

M-ITS-1303



ROADWAY WEATHER INFORMATION SYSTEM ROAD SURFACE SENSOR POLE DATE 1-31-2015