

I-13-4166 - ADA Improvement

I-14-4206 - Change in Conditions-Ground Improvement 3 & 4

RR-17-4291 - Sign Structure Plan Quantity Error

I-14-4220 - Supplemental to Monotube Engineering Costs

I-13-4104 - Structures Final Balance

I-13-4104 - Electrical Final Balance

I-15-4248 - Roadway Lighting Improvements

I-17-4323 - Field Office, Special

RR-16-5714 - MOT for ComEd Relocation

<u>I-14-4212 - Category B Structure Quantity Balance</u>

I-14-4642 - Delayed Roadway Work: Ramp M4 & North Thorndale Avenue

I-14-4178 - Adaptive Management

RR-16-4258 - Supplement to ATP #26 - Temporary Fueling

RR-16-5715 - Roadway Item Balancing

I-13-4618 - Maintenance of Traffic Prior to Acceleration

I-13-4617 - Construction Revision 2: Gap Lighting Adjustment Supplement

RR-16-4285 - Water and Sewer Connection Fees

I-14-4206 - Electrical Subcontractor's Delay Mitigation

I-15-4246RR - Tree Removal

<u>I-16-4264 - Camera Installation</u>

I-14-4638 - Repair Fiber Optic Cable Handholes

I-15-4237 - WB I-90 Pavement Patching

I-14-4207 - Structural Final Balancing 2

RR-15-4240 - Failed Patches Remediation

RR-13-4116 - York Road Structure

Page 1 As of 1/1/2019



RR-13-4116 - Winter Protection

I-13-4156 - Milling of Temporary Asphalt Wedge Supplement

RR-16-4285 - Temporary Fuel

<u>I-13-4156 - Pre-Stage Acceleration Supplement</u>

RR-17-4340 - Field Office

I-13-4166 - Material Cost Escalation

RR-14-5692 - DCEC-2 Request for Extended Overhead Compensation

I-14-4204 - Balancing Final Quantities - Roadway Lighting and Electrical Work Items #5

RR-15-9188 - Electrical Issues

<u>I-16-4670 - Remove Fly Dumped Material</u>

RR-15-8131 - Electrical Issues

RR-17-4340 - Bridge 14137 Accident Repairs

I-15-4237 - Extended Supervisory and Administrative Costs

I-14-4206 - Roadway Appurtenances Items Final Balancing - 5

RR-16-4273 - Preliminary Final Balancing of Roadway (Earthwork, Sub-Bases and Bases, and Pavements)
Line Items 2

I-13-4619 - Final Balancing - Roadway

RR-16-4285 - Construction Revision #02

RR-17-4291 - Roadway Pay Item Balancing

RR-17-5000 - Earthwork for DC-ACC1 & DC-ACC1A Relocation

I-13-4607 - Roadside Detector Salvage Cost

I-13-4618 - Electrical Item Balancing Supplement

I-14-4644 - Railroad Design Responsibility

I-13-4618 - Drainage and Erosion Control Item Balancing Supplement 2

RR-13-4116 - Temp Pavement Aggregate

Page 2 As of 1/1/2019



RR-13-4116 - Stage Revisions

RR-16-4258 - Construction Revision 4 Changes - Electrical

RR-17-4340 - Structure Repairs for Microsurfacing

I-13-4607 - Additional Mobilization and QC Costs

RR-17-5000 - Lower Level Generator Switchgear Room Revisions

I-16-4670 - Complete Curb Gap

<u>I-14-4644 - Final Balance Supreme Dr. extra Work Due to Delays</u>

<u>I-13-4618 - Roadway Item Balancing Supplement</u>

I-14-4644 - Final Balance Winter Inefficiency for Structures

<u>I-14-4644 - Final Balance Lively Revisions (CR6)</u>

RR-17-4341 - Class B Patching Quantities

I-14-4220 - Roadway Appurtenances Item Final Balancing-1

I-14-4638 - Procure ANPR Power Supplies

RR-17-5000 - Concrete Retaining Wall for DC-ACC1 & DC-ACC1A Relocation

RR-16-4256 - Combined Field Office

RR-16-4256 - Combined Field Office

RR-16-4285 - Grading Modifications for 4368 Building

RR-17-4291 - North Barrier Wall Extension

<u>I-17-4338 - Fiber Optic Cable Procurement</u>

RR-17-4341 - Class A Patching Quantities

RR-16-4254 - Somonauk Superstructure Repairs

I-13-4617 - Manzo's Banquet Driveway Drainage

RR-16-4285 - FA and Security Modifications for 4368 Building

RR-16-5714 - Year 3 Contract Extension

RR-16-4258 - Construction Revision 5 – US 20 Ramp Extension

Page 3 As of 1/1/2019



I-13-4618 - Extension of Temporary Signal Equipment

RR-16-4258 - Construction Revision 4 Changes - Mechanical

RR-16-4258 - Remote Radio Installation

RR-17-4340 - Bridge 14137 Accident Repairs - Supplemental

RR-16-4273 - Preliminary Final Balancing of Roadway (Earthwork, Sub-Bases and Bases, and Pavements)
Line Items 1

RR-13-4116 - Roosevelt Structure Repairs

I-13-4618 - Final Structural Item Balancing

RR-17-4349 - Lighting Improvements

RR-16-4253 - Issue No. 6 – Addenda Quantity Revisions

RR-16-4273 - Existing Subgrade Stabilization and Slab Jacking

RR-16-4273 - Dowel Bar Retrofit

I-14-4642 - Removal & Disposal of Excess Buried Conc Pavement

RR-16-4258 - Construction Revision 4 Changes - Architectural

I-15-4237 - Outside Lighting Maintenance - Supplemental

RR-16-4253 - Sign Truss Lighting Conduit & Wire

RR-16-4255 - Rumble Strip Removal

RR-16-4255 - Bridge Deck Overlay Protection

RR-16-4256 - Median Barrier Modification Protection

RR-16-4258 - Tree & Shrub Plantings

RR-16-4258 - Gateway Signage Improvements

RR-16-4256 - Bridge Deck Overlay Protection

RR-17-4337 - Drilled Shaft in Soil

I-17-4338 - Fiber Handhole Torsion Assist Lid

RR-13-4116 - Roosevelt Structure Repairs

Page 4 As of 1/1/2019



RR-16-4256 - Revised Paving Sequence

RR-16-4256 - Bridge Deck Overlay Protection - Supplemental

RR-13-4116 - Roosevelt Structure Repairs

RR-16-4254 - WMA Test Strips

RR-16-4254 - Mast Arm Cable Assemblies

RR-16-4273 - Dowel Bar Retrofit

RR-16-4255 - Rumble Strip Removal - Supplemental

RR-16-4255 - Bridge Deck Overlay Protection

I-18-4372 - PCC Pavement Patching in Lieu of Precast Panels

RR-16-4258 - Construction Revision 6-Driveway Entrances

RR-16-4256 - Bridge Deck Partial Depth Concrete Removal

I-14-4638 - Pavement Marking Refresh

RR-13-4116 - Winter Protection

RR-13-4116 - Mainline Pavement Repairs

RR-13-4116 - Electrical Revisions

RR-13-4116 - RACS System

RR-17-4340 - Defects within I-80 Co-ordination Limits

RR-16-4253 - Mast Arm Cable Assembly at IL-251 Ramps

RR-16-4253 - Mast Arm Modifications & Plan Revisions at IL-251

RR-18-9014 - Undercut with Geotechnical Fabric and PGE Aggregate Fill

RR-13-4116 - Soil Modification

RR-18-4351 - Rumble Strip Removal

RR-17-4346 - Plaza 21 Conduit Replacement

<u>I-15-4248 - Roadway Lighting Remediation</u>

RR-17-4341 - Additional Guardrail Repairs

Page 5 As of 1/1/2019



RR-17-4341 - Class B EB - Patching Quantities

I-17-4687 - Oty. Adjustment - Removal of Existing Approach Slab

RR-16-4255 - Bridge Deck Partial Depth Concrete Removal

RR-16-4255 - Additional Protective Shield at Warrenville Bridge

RR-17-4340 - Defects at WIM Pavement

RR-17-4340 - Slab Jacking at MP 8.1

RR-17-4340 - Defects at 55N to 355S Ramp

I-18-4389 - Quantity Adjustment NB Irving Park Gore

I-18-4389 - Emergency Pavement Repair

RR-17-4341 - Class B WB - Patching Quantities

RR-18-4351 - Non-Special Waste Certification

I-17-4687 - Type B Gutter Installation Ramp G5

RR-17-4341 - Custom Pre-Cast Concrete Pavement Slabs

RR-17-4347 - Construction Revision 1

RR-17-4348 - Construction Revision 1

RR-17-4340 - Unforeseen Additional Maintenance of Traffic

RR-18-4376 - Field Change No. 2

I-17-4687 - Undercuts in Embankment Area

RR-13-4116 - Roosevelt Recovery

RR-16-4256 - Noise Abatement Wall No 4 Modifications

RR-17-4340 - US Route 6 Ramps

RR-16-4255 - Additional Protective Shield at Finley Bridge

RR-16-5714 - Emergency Pavement Repair Allowance

RR-17-4344 - Additional Fast Deck Slab Repair Quantity

RR-16-4258 - Supplement to ATP #26/26.1 - Temporary Fueling

Page 6 As of 1/1/2019



RR-16-4258 - Supplement to ATP #38 - Cold Weather Concrete Placement

I-13-4617 - Final Roadway Balancing

RR-16-4285 - General Exhaust Piping

I-14-4638 - Pavement Marking Refresh - Supplement

RR-17-4313 - Rumble Strip Removal & Replacement

RR-17-4349 - Construction Revision #3

RR-18-4387 - Noise Wall Panel Remove and Reinstall (Concrete)

RR-16-4255 - Bridge Joint Repairs

I-18-4373 - Excavation to Allow

RR-16-4253 - BNSF East Slope Wall (WB)

<u>I-18-4389 - Construction Revison 2 – IDOT Permit MOT Revisions</u>

I-17-4688 - Mowing

RR-17-4314 - Field Office

RR-16-4256 - Bridge Deck Partial Depth Concrete Removal at Army Trail

RR-16-4256 - Additional Bridge Deck Latex Concrete

RR-16-4256 - Bridge Deck Partial Depth Concrete Removal

RR-16-4255 - Additional Bridge Deck Latex Concrete at Finley

RR-16-4256 - Additional Bridge Deck Latex Concrete at Fullerton

RR-16-4255 - Additional Protective Shield at BNSF Bridge

RR-17-4328 - Organic Soil Amendment

RR-16-4255 - Bridge Deck Partial Depth Concrete Removal

RR-16-4255 - Additional Bridge Deck Latex Concrete at Jackson

RR-16-4255 - Bridge Deck Partial Depth Concrete Removal at Jackson

RR-16-4256 - Drainage Frames and Grates Repair

RR-16-4256 - Additional Bridge Deck Latex Concrete at Oak Creek

Page 7 As of 1/1/2019



RR-16-4256 - Bridge Deck Partial Depth Concrete Removal at Roosevelt

RR-16-4256 - Additional Bridge Deck Latex Concrete at Roosevelt

RR-16-4256 - Bridge Deck Partial Depth Concrete Removal at IL Route 53

RR-16-4256 - Additional Bridge Deck Latex Concrete at IL Route 53

RR-16-4255 - Modifications to Concrete Median Barrier Transition, Type V-F

I-18-4388 - Median Barrier Wall Repair

I-18-4389 - Quantity Increase-Deck Slab Repair (Partial)

I-17-4688 - Double Handling

RR-17-5000 - Data Center Additional Receptacles

RR-16-4254 - Issue No 9 and 11 Guardrail Modifications

RR-16-4256 - Bridge Deck Partial Depth Concrete Removal at Oak Creek

RR-16-4256 - Bridge Deck Partial Depth Concrete Removal at Foxworth Blvd.

RR-16-4256 - Additional Bridge Deck Latex Concrete at Foxworth Blvd.

RR-16-4256 - Bridge Deck Partial Depth Concrete Removal at 22nd Street

RR-16-4256 - Additional Bridge Deck Latex Concrete at 22nd Street Bridge

RR-18-4362 - Additional Attenuator Hours

RR-16-4285 - Temporary Fuel

RR-16-4255 - Additional Bridge Deck Latex Concrete at Ogden

RR-17-4314 - Crack Filling

RR-16-4255 - Bridge Deck Partial Depth Concrete Removal at Ogden

I-18-4389 - Field Change 2

RR-16-4255 - Additional Bridge Deck Latex Concrete at Hitchcock

RR-16-4255 - Bridge Deck Partial Depth Concrete Removal at Hitchcock

<u>I-17-4687 - Maintain Existing Engineer's Field Office</u>

RR-17-4337 - Topsoil Excavation / Aggregate Replacement Inside Fenced Areas

Page 8 As of 1/1/2019



RR-17-5000 - Data Center Renovation Revisions No. 1 – Leak Detection System

RR-17-4345 - Controller Modifications

RR-17-4345 - Lighting Controller Duffy

RR-18-4362 - Unforseen Electrical Work

RR-16-5714 - Supplemental Pavement Marking

I-17-4687 - Slope Wall Repair on Ramp G5

RR-13-4116 - Fuel Cost

<u>I-17-4338 - Additional Work for Grand Ave Crossing</u>

I-17-4687 - Crashwall and Attenuator on Prospect Avenue

RR-17-4345 - Mast Arm Cable Assembly - Twist Arm

RR-17-4345 - Mast Arm Cable Assembly-Single Mast Arm

RR-18-4351 - Field Issue #4 - SW MSE Wall Redesign

RR-17-4346 - Mast Arm Cable Assembly-Twin Mast Arm

I-18-4369 - CR01-Building Removal No.10

RR-17-4397 - Topsoil Excavation/Aggregate Replacement Inside Fenced Areas

RR-17-4397 - Rock Excavation at Plaza 47

RR-17-4371 - Replace Landscaping with CA-7

I-17-4338 - Additional Work for North Ave Crossing

RR-13-4116 - Ramp F Pavement Removal

RR-13-4116 - Misc Erosion

I-14-4642 - Groundwater Infiltration

RR-17-5000 - Lower Level Dispatch of Data Center

RR-16-4255 - Paved Shoulder Removal

RR-17-4313 - 4312-4313 Dual Office Set-Up

RR-17-4340 - Defects at Spring Creek

Page 9 As of 1/1/2019



RR-17-4341 - VEP#2 - Expand Accelerated PCC CL B Patching for Lane 2 and Lane 3

RR-16-4258 - Floor Scrubbers

<u>I-13-4607 - Additional Disking and Drying Costs</u>

I-17-4687 - Loss of Production Due to Concrete Obstructions

I-18-4389 - Bensenville Bridge Interim HMA Deck Patching

RR-17-4345 - Field Issue #1

RR-16-4253 - Supplemental Bridge Repairs

RR-17-4398 - Replace Landscaping with CA-7

<u>I-18-4388 - Remove Cable From Conduit</u>

RR-17-4314 - Workzone Impact Attenuator Truck

I-18-4373 - Added Embankment

RR-13-4116 - WB Moment Slab

RR-13-4116 - Mainline Pavement Removal

RR-16-4255 - Temporary Maintenance of Traffic on WB I-88

RR-17-4312 - Category B Interim Balancing No. 1

RR-17-4312 - Category A Interim Balancing No. 1

RR-17-4314 - Additional Drainage and Erosion Control CR01

RR-17-4314 - IsU-1 Guardrail

I-18-4390 - ComEd Electrical Work - Supplement

RR-17-5000 - Additional MEP Work for DC-ACC1 & DC-ACC1A Relocation

RR-16-4255 - Incentive Proposal-Supplemental

I-18-4389 - Drainage Field Change

I-17-4687 - Qty. Adjustment - WMA Surface Course Mix D N70

RR-16-4255 - Rumble Strip Removal & Replacement – Final Balancing

RR-17-5000 - Data Center PDU-1 & PDU2 Replacement

Page 10 As of 1/1/2019



RR-17-4346 - Mast Arm Cable Assembly - Single Mast Arm

<u>I-18-4373 - Alternate Bridge Demolition Procedure</u>

RR-17-5000 - Telecommunications Room PDU-3 & PDU-4 Modifications

RR-13-4116 - Ramp Aggregate Removal

RR-16-4255 - Supplemental Bridge Joint Repair

I-18-4373 - Issue #1 - I-94 Plan Revision Request - Post Bid

I-18-4393 - Additional PCC Pavement

RR-17-4400 - Replace Landscaping with CA-7

I-18-4373 - Acceleration for Weather Related Roadway Delays

RR-13-4116 - EB 294 Moment Slab

RR-18-4401 - Roadway Quantity Adjustment

<u>I-18-4389 - Material Change Conduit Bores – PVC to CNC</u>

RR-18-4350 - Buckley Road Island Removal/Replacement

RR-17-4349 - Interim Balance-Electrical Items

I-18-4373 - Additional Acceleration for ComEd Delays

I-17-4322 - Acceleration Work

RR-18-4351 - Abutment Soil Reinforcement

RR-18-4351 - Additional Landscaping

RR-16-4258 - Tower Fencing Improvements

RR-17-4341 - Emergency Pavement Patching

RR-18-4371 - Spring Creek PL-99 (Site 355-1) Site Modifications

RR-18-4371 - 127th Street PL-93 (Site 355-2) Site Modifications

RR-17-4345 - Buckley Road Luminaire Hangers

I-14-4642 - Issue 101 – Mittel North Sewer Culvert Installation - Balance

I-18-4695 - ITS Power Relocate- Supplement

Page 11 As of 1/1/2019



RR-16-4254 - Temporary Pavement Marking Removal

<u>I-18-4388 - Mainline Pavement Repairs</u>

RR-18-4401 - HMA Removal Over Full Depth Patches

<u>I-18-4373 - Reinforcing Steel Acceleration for ComEd Delays</u>

I-18-4695 - Concrete Structures, Retaining Wall

RR-16-4256 - Splice Vertical Rebar at Retaining Wall No. 3

RR-16-4253 - Mast Arm Replacement (EB)

RR-16-4253 - Mast Arm Replacement (WB)

RR-16-4255 - Late Season Temporary Pavement Marking

RR-16-4258 - Supplement to ATP#71 - Construction Revision 6 Changes

RR-17-4313 - Truck Mounted Attenuator for Accelerated Patching Work

RR-17-4313 - Truck Mounted Attenuator for Precast Patching Work

I-18-4393 - Winter Protection

RR-17-4313 - Crack Routing & Sealing Along Resurfaced Joints

I-17-4687 - Loss of Production Due to Obstructions Balance and Close

I-17-4687 - Emergency Pavement Repairs Supplement

I-18-4373 - Additional Topsoil Excavation and Disposal

I-18-4373 - Additional Unsuitable Material Remove & Replace

I-18-4389 - Interim Balancing 1 - Roadway Items

<u>I-18-4839 - Interim Balancing 1 – Roadway Appurtenance Items</u>

RR-16-4254 - Blackberry Creek Superstructure Repairs and Supplemental

RR-16-4258 - Bury Downspout Drains and Supplement

RR-17-4313 - High Tension Cable Median Barrier Repair at WB MP 131.7 (Report #15-18-06220) & Spare Parts

<u>I-18-4389 - Interim Balancing 1 - Electrical Items</u>

Page 12 As of 1/1/2019



<u>I-18-4390 - Water Main Modification</u>

RR-13-4116 - Rumble Strip

RR-17-4313 - Temporary Epoxy Pavement Markings

I-17-4688 - Electric Service to K9 Facility

<u>I-13-4607 - Additional Disking and Drying Costs</u>

I-18-4391 - Construction Revision 2-Plaza 39 IPO

I-18-4389 - Acceleration / Delay Mitigation - Supplement

<u>I-18-4389 - Interim Balancing 2 - Structure Items</u>

I-18-4389 - Interim Balancing 2 - Electrical Items

I-18-4389 - Change to Fiber Cable

I-17-4338 - Northwest Ave Flagging

RR-17-5000 - Data Center Renovation Revisions No. 1 – Additional Rack Accessories

I-15-4237 - Touhy Underpass Lighting Production Loss

I-17-4338 - Unforeseen MOT Supplement

RR-16-4273 - Dowel Bar Retrofit

RR-16-4253 - Mast Arm Replacement

RR-16-5714 - SB Overlay Additional SMA Costs

RR-16-4255 - Supplemental Construction Revisions No 1, 2 and 3

RR-17-4291 - Extend Barrier Wall at Grand Ave Bridge

RR-17-4291 - Roadway Pay Item Balancing

I-13-4617 - Claim 6: Remove Thrust Block MWRD Sludge Line

RR-17-5000 - Data Center Hot Aisle Containment System Revisions

Page 13 As of 1/1/2019